GT-534 FAQ

Tables of Content

Q01 : What to do if I received a bad response from DI while using SMS command	
"@DIV" to check DI status?	3
Q02 : What to do if AI reset time of Utility can't write in flash of GT-534?	3
Q03 : How to set parameters if I want to connect to Utility?	3
Q04 : Why is GT-534 with VIBO system unable to register internet?	3
Q05 : How to update Firmware?	3

Q01 : What to do if I received a bad response from DI while using SMS command

"@DIV" to check DI status?

A01:

Please update firmware to 1.09 version

Q02: What to do if AI reset time of Utility can't write in flash of GT-534?

A02:

Please update firmware to 1.10 version

Q03 : How to set parameters if I want to connect to Utility?

A03:

You don't need to set the parameters; you only need to click the login of Utility.

Q04 : Why is GT-534 with VIBO system unable to register internet?

A04:

VIBO has 3G system only; it doesn't support GSM/GPRS system.

Q05 : How to update Firmware?

A05:

Please refer below step.

I. Power off GT-534. pin12 connect to (DC. +Vs), pin11 connect to (DC.GND), and connect RS-232 to PC.

II. Reboot GT-534 , GT-534 will enter "Firmware update mode" (light 800ms / dark 200ms)



- III. Execute Firmware Update tool :
 - (1) select com port
 - (2) select new firmware [,] as below is "firmware name(ex.GT534_V1.08.fw)"
 - (3) click "Firmware Update" button. if update success, it will show "update success"
 - (4) disconnect pin12, and reboot to finish update

募 Firmware Update Tool v1.04	
1. Download Interface COM COM Port : C USB	www.icpdas.com
2. Firmware Path	
D:\GT-534資料\GT-534 FW Update\GT534_v1.08	fw Browser
3. Firmware Update	
Click "Firmware Update" button to start firmware	updating !! Firmware Update
	Exit

募 Firmware Update Tool v1.04	
1. Download Interface COM COM Port : C USB COM1	www.icpdas.com
2. Firmware Path	
D:\GT-534資料\GT-534 FW Update\GT534_ - 3. Firmware Update	v1.08.fw Browser
Firmware Update Success ! Please Reboot Mo	odule !
	Firmware Update
	Exit